PX9020



measuring range	0-400 bar
material	V4A
output signal	0,5-4,5 V
connection thread	G1/4IG (adapter 52438 required)

for furling systems

Real-time adjuster pressure sensors allow the current load on the forestays to be measured.
Our stainless steel pressure sensors have a measuring range of 0 to 400 bar with different analogue output signals available.
On request, we can also deliver the sensors with digital bus outputs.



Reckmann pressure transmitter